

## **Release Notes for DrayTek Vigor2830 series (UK/Ireland)**

### **Single band for wireless models**

|                   |  |
|-------------------|--|
| Firmware Version  | 3.7.0 sb   |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient           |
| Release Date      | 28 <sup>th</sup> February 2018                                 |
| Build Date        | 7 <sup>th</sup> February 2018                                  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| Revision          | 71466  |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

#### **New Features**

1. Support for additional TR-069 parameters to configure [System Maintenance] > [Management] settings through VigorACS

#### **Improvements**

(None)

#### **Known Issues**

1. Before upgrading firmware, take a configuration backup. After upgrade to 3.7.0 it is not possible to revert and downgrade to a firmware version prior to 3.6.8.6 without resetting the unit. To downgrade from 3.7.0 firmware, reflash earlier firmware using .rst firmware and reload the configuration backup from the previous firmware version
-

## **Firmware File Types**

The ZIP file contains the firmware with two different file extensions, .ALL and .RST. The firmware is identical but the RST file contains factory default settings. If you install the ALL file, your router will retain all existing settings. If you use the RST file, all settings will be wiped from your router.

## **IMPORTANT NOTE - Wireless**

If your Vigor 2830 unit is a wireless model then this firmware is only suitable for SINGLE BAND models. All 'plus' units are Dual-Band so should not use this firmware. Most non-Plus units sold from approximately July 2011 onward are single band. Non-Plus units sold before August 2011 may be single or dual-band.

If you use the wrong firmware, your wireless will not work. If you're not sure which type you have, check this guide:

<http://www.draytek.co.uk/support/guides/kb-vigor-2830-dual-band>

## **IMPORTANT NOTE – Hardware Versions**

This firmware is for use with the Vigor 2830 version 1 hardware, not the 'v2' (version 2) unit. Check this guide to confirm which hardware version you have:

<http://www.draytek.co.uk/support/guides/kb-v2830n-v1-vs-v2>


## **NOTE: ADSL Modem Codes**

- For general purpose usage on UK lines, modem code 232201 is recommended.
- For ADSL2+ Annex M lines, the latest modem code 2471201 is suggested.
- For line speeds of less than 4Mbps, on lower quality lines a modem code with more conservative parameters, 211801 is suggested

## **Upgrade Instructions**

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the router's system maintenance menu.

To upgrade firmware, select '*firmware upgrade*' from the router's system maintenance menu and select the correct file. Ensure that you select the ALL file unless you want to wipe out your router's settings back to factory default.



## **Manual Upgrade**

If you cannot access the router's menu, you can put the router into 'TFTP' mode by holding the RESET whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier and recommended – this manual mode is only needed if the web interface is inaccessible.

---

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.9 sb   |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient           |
| Release Date      | 3 <sup>rd</sup> January 2018                                   |
| Build Date        | 7 <sup>th</sup> December 2017                                  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| Revision          | 70391  |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

1. EAPOL Key Retry Enable/Disable setting added to [Wireless LAN] > [Security] Disabling this setting can prevent WPA2 Key Reinstallation Attack (KRACK) attack vectors, for more details please read this security advisory:  
<https://www.draytek.co.uk/information/our-technology/wpa2-krack-vulnerability>  
(EAPOL Key Retry is set to Enabled by default and in previous firmware)

### **Improvements**

1. TR-069 (TCP & UDP 8069) Internet access control now controlled by Access List
2. Improved LDAP server interoperability when authenticating L2TP with IPsec connections
3. Improved display of VoIP Status information with Firefox browser

### **Known Issues**

2. Before upgrading firmware, take a configuration backup. After upgrade to 3.6.9 it is not possible to revert and downgrade to a firmware version prior to 3.6.8.6 without resetting the unit. To downgrade from 3.6.9 firmware, reflash earlier firmware using .rst firmware and reload the configuration backup from the previous firmware version

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.8.7 sb   |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient<br>Note: A previous firmware (3.6.8.6) was a <b>critical release</b> . This f/w includes all changes/improvements that were in 3.6.8.6. |
| Release Date      | 21 <sup>st</sup> September 2017  |
| Build Date        | 26 <sup>th</sup> July 2017   |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band)   |
| Revision          | 67375  |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

2. Support for extra TR-069 parameters

### **Improvements**

(None)

### **Known Issues**

1. Before upgrading firmware, take a configuration backup. After upgrade to 3.6.8.7 it is not possible to revert and downgrade to a firmware version prior to 3.6.8.6 without resetting the unit. To downgrade from 3.6.8.7 firmware, reflash earlier firmware using .rst firmware and reload the configuration backup from the previous firmware version

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.8.6 sb   |
| Release Type      | <b>Critical</b> – Upgrade recommended immediately              |
| Release Date      | 20 <sup>th</sup> December 2016                                 |
| Build Date        | 6 <sup>th</sup> December 2016                                  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features in this Firmware**

(None)

### **Improvements in this firmware**

1. Security improvements including one or more considered critical.
2. Misc. minor WUI changes/corrections.
3. Resolved an issue with PPTP VPN Passthrough for NAT to some types of internal PPTP VPN server

### **Known Issues**

1. Before upgrading firmware, take a configuration backup. After upgrade to 3.6.8.6 it is not possible to revert and downgrade without resetting the unit. To downgrade from 3.6.8.6 firmware, reflash earlier firmware using .rst firmware and reload the configuration backup from the previous firmware version

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.8.5 sb   |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient           |
| Release Date      | 1st November 2016  |
| Build Date        | 12th August 2016   |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

1. Router auto-generates unique Self-Signed Certificate for HTTPS upon firmware upgrade
2. Added options in [System Maintenance] > [Management] to disable HTTPS management via TLS 1.0, TLS 1.1 or TLS 1.2

### **Improvement**

1. Session validation method improved in Web UI

### **Known Issues**

1. Before upgrading firmware, take a configuration backup. After upgrade to 3.6.8.5 it is not possible to revert and downgrade without resetting the unit. To downgrade from 3.6.8.5 firmware, reflash earlier firmware using .rst firmware and reload the configuration backup from the previous firmware version
2. PPTP VPN Passthrough for NAT to some types of internal PPTP VPN server may prevent a VPN establishing successfully

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.8.4 sb   |
| Release Date      | 6th February 2016  |
| Build Date        | 19th January 2016  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

1. Web Server and SSL VPN supports TLS 1.2

### **Improvement**

1. Improved TCP SYN protection mechanism

### **Known Issues**

(None)

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.8.3 sb   |
| Release Date      | 29th December 2015   |
| Build Date        | 22nd October 2015  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

1. Web Server and SSL VPN supports TLS 1.2

### **Improvement**

1. Resolved some issues with Web Portal function
2. Support for TR-069 HTTP/HTTPS trigger, available in [System Maintenance] > [TR-069] "Test with Inform" button



|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.8.2 sb   |
| Release Date      | 20th May 2015  |
| Build Date        | 8th May 2015   |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

(None)

### **Improvement**

1. [System Maintenance] > [TR-069] now has a Wizard button to enter the address of the ACS server with the required URL.
2. DHCP Option 66 now supports special characters such as \$ (through CLI, using "srv dhcp option" command).
3. An issue that caused problems with LAN DNS and DNS Caching has been resolved.
4. Support for the MF825A USB modem.
5. Resolved a DHCP issue with [WAN] > [Multi-VLAN] - Port Based Bridge mode
6. Access List for router management was not working correctly when using a LAN to LAN VPN as the default route.
7. Resolved an issue with the Firewall that could stop users accessing the internet due to a session limit error under some circumstances.
8. User management was not working correctly when using User-Based mode.

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.8 sb   |
| Release Date      | 4th February 2015  |
| Build Date        | 20th January 2015  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 211801   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

(None)

### **Improvement**

1. SSL3 now disabled in favour of TLS by default for SSL tunnels and web management.
2. Added TR-069 parameters to configure SNMP management.
3. Support for RFC3021 (Using a /31 Subnet Mask WAN interface).
4. Corrected issue that may have prevented fail over to a 3G Backup interface after 36 days of uptime.
5. SIP phones connected to the router's LAN could experience issues with registration under specific circumstances.
6. Added telnet command to disable/enable LAN ports - "port enable/disable x".
7. Added TR-069 parameter to disable/enable LAN ports.

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.7.2 sb   |
| Release Date      | 13th August 2014   |
| Build Date        | 8th July 2014  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

(None)

### **Improvement**

1. Corrected data reported in SNMP OID: 1.3.6.1.2.1.1.1
2. Improved memory handling of PPPoE disconnection event

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.7.1 sb   |
| Release Date      | 11th July 2014   |
| Build Date        | 18th June 2014   |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 211801   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

1. User Defined Daylight Saving
2. DNS Cache Table

### **Improvement**

1. Updated SSL for CVE-2014-0224
2. Resolved issue of firewall blocking IPv6 incoming routing traffic.
3. Load Balance/Route Policy didn't work with WAN5 in PPP mode.
4. Load Balance/Route Policy cleaned all sessions when the dropped down WAN reconnected
5. DDNS could not work when updating to freedns.afraid.org
6. Could not add DHCP option 66/15.
7. Router showed wrong Syslog messages when a VPN LAN to LAN tunnel drops
8. Router dropped all DNS packets with unknown type.
9. SSH didn't work with mac OS
10. VigorACS SI couldn't show Network information when DNS Filter was enabled for Vigor2830.
11. External Device Status page improved
12. Remove Mhaha, getMessenger, IMUnitive, Wablet from WebIM on CSM>>APP Enforcement Profile.
13. Support to block LINE app in 3.5.1.36 (for PC) version and in 4.1.1 version (for mobile) for APP Enforcement.
14. Support block page for DNS filter.
15. Route policy supports VPN LAN to LAN traffics.
16. In LAN > Web Portal Setup. Option added to force the user clicking OK button before proceeding

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.7 sb   |
| Release Date      | 13th March 2014  |
| Build Date        | 26th Feb 2014  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

## **New Features**

1. Support IPv6 6in4 Static Tunnel service, IPv6 6rd Tunnel service and IPv6 NTP service.
2. Support new route policy. <http://www.draytek.co.uk/support/guides/kb-policy-routing-guide>
3. Support [CSM]>DNS Filter to allow CSM to make decisions based on DNS requests  
<http://www.draytek.co.uk/support/guides/kb-dns-filter>
4. Support [Applications]>LAN DNS. <http://www.draytek.co.uk/support/guides/kb-lan-dns>
5. Support "USB Device Status" gives status of devices connected via USB
6. USB modem support list added to Web UI but also see  
<http://www.draytek.co.uk/support/guides/usb-3g-4g-modem-support-list>
7. "APPE Support List" added to Web UI
8. Support [Wireless LAN] > [Bandwidth limit] Auto adjustment to allow automatic control over the available bandwidth
9. [Management]>[LAN Access Control] allows control over which subnets can access the routers management interfaces
10. Support added for multiple Phase2 SA through one VPN tunnel. Each subnet is defined in "More">"Create Phase2 SA for each subnet".
11. Previously one tunnels per subnet would be needed for VPN between other vendors eg Cisco crypto

## **Improvement**

1. Additional USB modem support inc. Support Huawei E303D, Vodafone K4201, SpinCom GPRS Modem, vodafone K3772-Z, Infinity IW-021, Option iCON XY modems
2. Improved: Support NS/ANY/SOA type for DNS cache.
3. Additional option to firewall to control incoming non-nat packets for IPv6 and IPv4If the firmware of the router is upgraded from 3.6.6(or before) to 3.6.7 firmware, .all and .rst will have different effects for the incoming packets.
  - 1) .all --> allow routing settings in 3.6.6(or before), (both IPv4 and IPv6)
  - 2) .rst --> block routing packets from WAN in default, (both IPv4 and IPv6)
1. Add some TR-069 parameters for setting WAN >> WAN mode: Backup or Always On, LAN >> DHCP relay enable/disable, DHCP relay IP address and Device hostname, LAN >> Bind IP to MAC, VPN >> Create Phase2 SA for each subnet.(IPSec), VPN >> Netbios Naming Packets Pass/Block, Firewall >> IPv6 Group/IPv6 Object, SNMP, and Diagnostics >> Ping Diagnosis.
4. Support to block Tor tunnel ver. 0.2.3.25, hotspot shield with ver.3.19, and telnet protocol by using "putty" or "pietty" for APP Enforcement.
5. Add SSL VPN setting in VPN Server Wizard.

6. Add Wizards menu.
7. Corrected some DHCP relay issues
8. Fixed a SSH memory leakage issues.
9. Load Balance/Route Policy didn't work with WAN5 in PPP mode.
10. Corrected: Load Balance/Route Policy cleared all sessions when a WAN reconnects
11. DDNS did not work when updating to freedns.afraid.org
12. Now allows DHCP option 66/15 to be added
13. Corrected syslog message when a VPN LAN to LAN tunnel drops
14. Router dropped all DNS packets with unknown type.
15. Daylight Saving didn't work with time zone Brasilia (GMT -03:00).
16. SSH didn't work with Macintosh
17. VigorACS SI couldn't show Network information when DNS Filter was enabled for Vigor2830.
18. Default Route over VPN was not resumed after VPN backup worked.
19. Could not set QoS control by ACS server / TR069
20. Could not set QoS service type/QoS DSCP by telnet.
21. Improved behaviour of telnet 'qos class -V' command
22. The router dropped negative AAAA name server responses from different subnets.
23. Improved memory handling of IPsec aggressive mode.
24. Improved handling of DNS responses with VLAN tag.
25. The SNMP LAN status corrected
26. Corrected that Load-Balance/Route Policy might cause Remote Dial-In users not accessing into internal PCs.
27. MOTP could not work when "PIN code" is set in 4-digit and "Secret" is set in 16-digit.
28. Turn off specific 5 GHz channels where DFS is required.
29. Port triggering could only work when first profile has been set.
30. Resolved issue with Session Limit after enabling the smart bandwidth limit.
31. QoS Outbound for WAN1 now recognizes UDP 500, 1701, and 4500
32. Fixed that File Explorer would show 1KB when the file size is more than 2GB.
33. Improved handing of USB modem detection/insertion
34. Shrewsoft VPN Client cannot connect twice from the same public IP address.
35. Corrected that re-dial of LAN to LAN VPN might not occur if VPN server was unavailable but then available again
36. Correct that all WCF profile would display as empty if Index 8 WCF profile name contains a space
37. Corrected issue if user management policy rule was set to 7th rule
38. Cannot create a new profile by APP Enforcement Profile Wizard.
39. Fetch the diagnostics NAT session values from ACS server
40. SIP ALG did not convert "Via" field in 200 OK.
41. Improved NAT loopback performance.
42. Added auto removal of inactive DHCP clients
43. Improved: DHCP table shows conflict IP Address.
44. Corrected that the router may drop ISP sends DHCP packets with TTL=1
45. Improved Bind IP to MAC function
46. Improved UPnP

47. Fixed the "Old Password is wrong, please re-enter" error that could occur after adding a new local user with administrator authority.
48. Added support for "www.lusosms.com" SMS service
49. Support special character "." on Wireless SSID.
50. Support telnet commands such as "portmaptime" and "vigorddns".
51. Support GRE over IPsec keepalive which for compatibility with Cisco routers
52. Allow SSL VPN portal if SSL VPN service is enabled regardless of if Internet access is enabled or disabled.
53. Change the default setting from "Both: Pass" to "Either: URL Access Control First" on URL Content Filter Profile.
54. Modified DoS default values.
55. Update new pattern for Ultrasurf 13.01, else it will block some the certificates.
56. Support "Hotspot shield" v2.93 blocking.
57. Support PPTV v3.3.8.0031 for new video and PPTV web blocking, LINE for PC and mobile phone blocking.
58. Support embedded flash videos blocking.
59. Support TR-069 parameters for WLAN WDS.
60. Support TR-069 parameters displayed on Diagnostics >> Routing Table.
61. Add a "LinkStatus" key to the TR-069 WAN information to indicate accurate connection status.
62. Increased input number from 10 to 29 digits for Call Barring.

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.4.1 sb   |
| Release Date      | 26th Sept 2013   |
| Build Date        | 16th July 2013   |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

1. Support the parameters settings for TR-069 server/port number in System Maintenance>>Management page.

### **Improvement**

1. Corrected: Prevent Access to Web UI via HTTP being blocked due to infinite HTTPS loop.
2. Corrected: LAN PC cannot access web user interface via router's WAN Alias IP.
3. Added protection to cater for enabled but unconfigured LAN to LAN or Dial-In user profiles.
4. Improved L2TP WAN2 Access mode
5. Note added in [System Maintenance]>[Management] to alert users if the SSL Tunnel service is using TCP 443
6. Improved: Add a note to remind customers that SSL and HTTPS use the same port.

### **Known Issue**

(None)



|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.4 sb   |
| Release Date      | 7th May 2013   |
| Build Date        | 19th March 2013  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 211801   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

1. SSL VPN support up to 5 dial-in users
2. Added Web Portal (displays message on connection) in [LAN] – [Web Portal Setup]
3. Added Wireless Configuration Wizard.
4. IPv6 USB LPR printing service.
5. Mail Alert now supports sending mail via SSL / TLS and can specify the SMTP port
6. Web content feature DNS mechanism during activation/authentication improved
7. Web interface can be authenticated through LDAP or user accounts configured from [System Maintenance] – [Admin Setting]
8. Admin Login through WAN can now be disabled
9. DHCP options (ASCII/Hex) can be set under [LAN] – [General Setup]
10. Added a VLAN failsafe option to the [LAN] – [VLAN] section
11. Added an “Always On” checkbox for IPv6 – AICCU tunnel
12. Add VoIP Inter-digit timeout for TR-104.
13. Added a telnet command to set which ADSL modulation types are used with the Modulation set to Multimode: % adsl automode [add|remove|set|default|show][adsl\_mode]

### **Improvement**

1. Router’s handling of AICCU neighbour packets.
2. Time and Date: Daylight Saving doesn't work with time zone Adelaide (GMT +9:30).
3. An issue with sending pings between VLAN subnets
4. 4G WiMAX / LTE web user interface settings could not be saved.
5. VPN: Windows 7 L2TP over IPsec client could not pass traffic immediately after connecting
6. Improved processing of multiple simultaneous PPTP dial in/out connections
7. VPN: If MPPE was enabled, the PPTP Dial-in user VPNs could not connect
8. VPN: IPSec LAN to LAN VPN tunnel could not pass PPTP VPN traffic
9. VPN: PPTP Dial-in user VPNs could not create a PPTP VPN through that tunnel
10. WLAN: Incorrect country code sent which affected Mac and Linux computers connecting wirelessly on channels 12 and 13
11. WLAN: Router was broadcasting SSID when wireless was disabled by schedule
12. The RADIUS request of WLAN clients was rejected by Synology NAS RADIUS server
13. Two IP phones behind NAT are unable to call each other after a period of time
14. SIP ALG: "via" information was not being modified correctly
15. App Enforcement: Now supports blocking RaidCall (v7.0), PPStream (v2.7.0.1512), and Teamviewer (v8.0.16284, v7.0.15723).
16. Load Balance Policy: can now specify a VPN tunnel to pass traffic through

17. Supports connecting to an LDAP Server via hostname.
18. SMS Alert: Added support for "messagebird.com" SMS Service.
19. H.323\_alg passthrough support
20. [NAT] – [Open Ports]: can now specify All as a WAN option
21. Time and Date: Modified the NTP DNS resolution period from once every 20 seconds to 10 seconds prior to the time specified by Automatic Update Interval.
22. Corrected routing for WLAN SSID broadcast packets
23. SNMP: IP Routed subnet IP of router would not respond on SNMP
24. The router accepts asterisk (\*) as the administrator password.
25. [LAN] – [LAN Port Mirror]: Restart no longer required after changing settings
26. Improved: Web Content Filtering: When the user accesses a website present in two categories with Commtouch, the router can only show/handle one category.

### **Known Issue**

1. The SSL VPN function uses port 443. If NAT redirecting port 443 to an internal server please change the routers SSL VPN port via [SSL VPN]>[General Setup]
2. MoTP Dial-In User profiles cannot be saved via Web UI. A work around is to setup PPTP without MoTP and then use telnet to enable.

```

> vpn dinset ?
% vpn dinset
% vpn dinset <list index>
% vpn dinset <list index> <on/off>
% vpn dinset <list index> motp <on/off>
% vpn dinset <list index> pin_secret <pin> <secret>
> vpn dinset 1
Dial-in profile index 1
Profile Name: motep
Status: Active
Mobile OTP: Disabled
Password: 1234
Idle Timeout: 300 sec
> vpn dinset 1 motp on
% Enable Mobile OTP mode!
> vpn dinset 1 pin_secret 1234 123456789abd1234

```

|                   |  |
|-------------------|--|
| Firmware Version  | 3.6.3 sb   |
| Release Date      | 11st Oct 2012  |
| Build Date        | 4th Oct 2012   |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

1. IPv6 Support added
2. Support for Smart Bandwidth Limit added
3. SNMP v3 support added
4. Support for QoS DiffServ retagging added
5. Support ADSL PVC to PVC binding
6. VoIP Wizard added
7. Each LAN Subnet now supports setting an individual DNS setting
8. New SMS & Mail Service Object added
9. New load-balance policy function supports the routing requirements for IP routing subnets
10. User Management now supports Web Authentication using either HTTPS or HTTP

### **Improvement**

1. Resolves an issue that could prevent correct Static route functionality when multi-subnet is enabled
2. Corrects a Routing table display error in [Diagnostic] > [Routing Table] menu
3. Corrects the LAN interface that is displayed for static ARP
4. Resolves an issue that could prevent two computers within the same VLAN from communicating with each other when connecting via different switches
5. Fixes an issue in IGMP snooping which would prevent two IPTV clients from watching the same channel
6. Corrects an issue that could cause Dynamic DNS to force update even though there was no WAN IP change
7. Removed incorrect PPP start (xxx) log entry where incoming client is unknown prior to CHAP/PAP authentication
8. Addresses an issue that would prevent Android phone from obtaining FTP file list from Vigor 2830 FTP server
9. Corrects an issue where NAT port redirection for a WAN1 Alias IP doesn't work when port redirection setting doesn't specifically list the Alias
10. Addresses an issue with True IP DMZ
11. Resolves configuration issues that could occur in [WAN] > [General Setup]
12. Wireless country string corrected
13. Addresses an issue that could occur with the wireless AP Discovery feature
14. Improved Wireless 802.1x compatibility with linux Radius Server
15. Resolves an issue which would prevent IP Phones behind the Vigor 2830 from registering after a WAN failover because the router would send UDP packets with a source port of 0.

16. Fixes an issue with sending DHCP Relay via VPN tunnel
17. Addresses an issue with GRE IPsec tunnels
18. Resolves an issue that would prevent AES192 or AES 256 being used as the IKE proposal if AES without authentication is selected as the IPsec Security method
19. Corrected firewall so that is able to block internal router subnet packets
20. URL Content Filter Syslog improved so that it displays HTTP or HTTPS
21. Resolved an issue that would prevent external client from access internal RDP server via IP routing subnet
22. Fixed an issue that would prevent wireless clients successfully completely 802.1x authentication after router reboot
23. Incoming ICMP packets from WAN side cannot ping "IP routing subnet" interface IP
24. Fixed an issue that could case CPE to loss connection when it connects to VigorACS server with STUN server.
25. Improvements to WCF service stability
26. Clear button added to SIP account page
27. DHCP Server Lease time field added for each subnet.
28. Syslog improved to show which devices have been allocated IP by router
29. Added support to allow the router to send the TR-069 packet out via LAN interface
30. Support GRE over IPsec with CISCO. (4 bytes GRE header)
31. Modified the default pool size of LAN DHCP server from 50 to 150.
32. Correct error with Secondary DNS displayed in Online Status
33. Added new DDNS provider (UBDdns, Oray, and Peanut Shell).
34. Improve Samba compatibility with Mac OS X.
35. Bandwidth Limit range changed to 0 - 30000
36. Port Redirection can shows WAN Interface for each rule in the main page.
37. For Safari based browsers the User Management redirection page method has been improved
38. Application Filter updated to support dropbox version 1.4.11 and skype version 5.10.56.116.
39. ADSL state information update frequency decreased from 5 to 30 seconds
40. "Undefined Protocol" DoS defense function renamed as "Unassigned Numbers"
41. Updated 3G modem support including MF190J, AnyDATA ADU-500A, LG VL600 LTE, and LTE Yota LU150.
42. Improved the connection performance for Huawei E398/K5005 and Sierra 320U dongle.
43. Default QoS setting changed to disabled for non-VoIP models
44. QoS for VoIP enhanced
45. ALG for SoftPhone Polycom and lift-size improved
46. VPN Profile WUI improved
47. UCF/WCF block web page modified
48. SNMP's sysDescr now shows model name and firmware version.
49. TR-069 support added for IP Route subnet parameters, firewall parameters, RADIUS parameters, WAN Connection Detection and SysLog / Mail Alert Setup parameters
50. 3G WAN connection Signal parameter status added to TR-069
51. Renamed TR-069 parameter  
"InternetGatewayDevice.X\_00507F\_Firewall.DoSDefense.BlockUnknownProto" to
52. "InternetGatewayDevice.X\_00507F\_Firewall.DoSDefense.BlockUnassignedNum"

53. Added a telnet command to configure IGMP Query packet interval time. 'ip igmp\_proxy query [msec]'
54. Added a telnet command to configure flash hook minimum and maximum time for VoIP.
55. Added a telnet command to allow VPN packets to instead go through by NAT if VPN disconnected: 'vpn pass2nat <on/off>'
56. "ip arp accept" telnet command changed to give separate control over behaviour (pass or block) for both incorrect source mac and incorrect destination mac. 'ip arp accept <0/1/2/3/status>'
57. Corrected: A router without VoIP module should not have an option "VoIP" in Multi-PVCs setting page.

### **Known Issues**

(None)

|                   |  |
|-------------------|--|
| Firmware Version  | 3.3.7.1 sb   |
| Release Date      | 1st June 2012  |
| Build Date        | 22nd May 2012  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201   |
| Locale            | UK Only / Annex A Only   |

### **New Features**

1. Support PVC WAN routing in static route.
2. Support IP Routing subnet parameters (for TR-069).
3. Support login customization (can be configured in System Maintenance > Login Customization).
4. Support USB 56K modem.
5. Support 3G USB modem, ZTE K3806 (0x19D2:0x1013) and ZTE MF192 (0x19D2:0x1514) and QT-R220.

### **Improvement**

1. Corrected: Wireless client cannot access LAN network from other AP and then return to use the wireless LAN interface of Vigor2830.
2. Corrected: Syslog displays http://xxxxx rather than https://xxxxx when CSM blocks HTTPS URL due to keyword object "xxxxx".
3. Corrected: The minimum value is 48 seconds for the session-timer setting in VoIP >>Phone Settings.
4. Corrected: Remove "Ultrasurf" from WUI.
5. Removed ADSL2/2+ Annex M from "multimode" auto-detect mechanism due to interoperability issues that could cause incorrect modulation to be set. For Annex M lines please manually set the modulation to Annex M instead of multimode.
6. Corrected: The router always shows "LAN1" after setting a new static route to the subnet of LAN2/LAN3/LAN4.
7. Corrected: Creating a UCF (URL Content Filter) keyword object "xxxx" could block access to HTTPS sites other than ones that match https://xxxx

|                   |  |
|-------------------|--|
| Firmware Version  | 3.3.7 sb   |
| Release Date      | 1st March 2012   |
| Build Date        | 9th February 2012  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 2471201  |
| Locale            | UK Only / Annex A Only   |

### **New Features**

1. Support SMS (Shore Message Service). When WAN backup mechanism is activated the system administrator can be notified via a SMS message to their mobile.
2. Support Common E-mail / Send Syslog via email.
3. Support Auto-detection mechanism.
4. Support GRE over IPSec
5. Support ADSL2/2+ Annex J and Annex M detection added to multimode modulation mode.
6. Support Address Mapping for NAT configuration.
7. Support hardware MD5/SHA1 encryption.
8. Allow Mail Alert to send emails with VPN notifications.
9. Allow the router to be managed and controlled by SmartMonitor.
10. Support 56K AFM102 USB Modem.

### **Improvement**

1. Improved: Add a new telnet command "voip sip misc -D" to disable/enable VoIP service.
2. Improved: Add a new telnet command "srv dhcp custom\_option" which allows a user to enter user-defined "DHCP option".
3. Improved: Support disable/enable user mode on WUI. The factory default setting is disabled.
4. Improved: Improve the compatibility with VigorACS SI v1.08
5. Improved: SIP address format (either Withheld@.. or anonymous@.. ) can be blocked if
  1. Block Anonymous under VoIP>>DialPlan>>Call Barring is configured.
6. Improved: Incoming calls with SIP from header field without having an account name
  2. (e.g., tagged with 5E623524-172D) can be blocked if Block Anonymous under
    3. VoIP>>DialPlan>>Call Barring is configured.
7. Improved: Corrected some SNMP reporting for LAN status
8. Improved: Support Syslog Explorer with Web Syslog and USB Syslog under USB
  4. Application.
9. Corrected: DDNS does not upgrade automatically when the DDNS account is set for WAN2 only.
10. Corrected: Data Flow Monitor does not show TX value for the monitored IP address and RX value for WAN1 on PPTP Host-LAN environment.
11. Corrected: Cannot connect VPN via 3G (WAN3) when WAN1 or WAN2 is connected.
12. Corrected: RIP over VPN does not work.
13. Corrected: My WAN IP setting does not work for PPTP in VPN NAT mode.
14. Corrected: Cannot create LAN-to-LAN VPN connection via WAN3 when WAN1 or WAN2 is connected.

15. Corrected: My WAN IP setting does not work for PPTP in VPN NAT mode.
16. Corrected: Buffer leakage when IPSec Aggressive mode is used and set with local IP address.
17. Corrected: User-Based mode of user management does not work if HTTPS management port has been changed.
18. Corrected: WAN cannot get IP from DHCP server when Block Fraggle Attack is checked in the page of Firewall>>DoS Defense.
19. Corrected: Ping detection failed when target IP and gateway are in the same subnet.
20. Corrected: When WAN 1 is disconnected, the router cannot send the SIP register packets of internal VoIP phones via WAN2 port automatically.
21. Corrected: VigorPhone350 loses registration behind NAT after one or two weeks
22. Corrected: NAT improvements to previous VoIP calls disconnecting after 2-3 minutes



|                   |  |
|-------------------|--|
| Firmware Version  | 3.3.6.1sb  |
| Release Date      | 1st July 2011  |
| Build Date        |  |
| Applicable Models | Vigor2830, Vigor2830n (Single band), Vigor2830Vn (Single band) |
| ADSL Modem Code   | 232201 (Standard)  |
| Locale            | UK Only / Annex A Only   |

**First Firmware Release for this model**

**[END OF FILE]**







