

## **Release Notes for DrayTek VigorAP 910C (UK/Ireland)**

|                   |   |
|-------------------|---|
| Firmware Version  | 1.3.5   |
| Release Type      | <b>Critical</b> – Upgrade recommended immediately |
| Release Date      | 27 <sup>th</sup> April 2023                       |
| Build Date        | 21 <sup>st</sup> March 2023                       |
| Revision          | g1572_0c594a29d9                                  |
| Applicable Models | VigorAP 910C                                      |
| Locale            | UK Only   |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

(None)

### **Improvements**

1. DNS security improvements (CVE-2022-30295)
2. Open SSL security improvements (CVE-2022-0778)
3. Tagged 2.4GHz SSIDs could fail to provide IPv6 traffic

### **Known Issues**

(None)

## **Firmware File Types**

The ZIP file contains the firmware with a file extension of .ALL. If you install the ALL file, your access point will retain all existing settings. Changing the file extension to .RST and uploading that firmware file will reset the VigorAP to its Factory Default configuration.

## **Important Note - DO NOT POWER OFF WHEN UPDATING FIRMWARE**

When updating from 1.1.3.2 firmware, this firmware updates the bootloader of the access point in addition to the firmware, this means that the access point will reboot twice.

It is essential that the access point is not powered off during this time as it may put the access point into an unrecoverable state. This can take up to 3 minutes when updating locally.

## **Upgrade Instructions**

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the AP's system maintenance menu.

To upgrade firmware, select '*firmware upgrade*' from the AP's system maintenance menu and select the correct file. The access point will perform the upgrade and automatically reboot once this completes.



## **Manual Upgrade**

If you cannot access the AP's menu, you can put the AP into 'TFTP' mode by holding the FACTORY RESET button whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier and recommended – this manual mode is only needed if the web interface is inaccessible.

---

|                   |  |
|-------------------|--|
| Firmware Version  | 1.3.4  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 01 <sup>st</sup> October 2021                        |
| Build Date        | 09 <sup>th</sup> September 2021                      |
| Revision          | g961_2f4e742   |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

(None)

### **Improvements**

1. Updated wireless chipset drivers to resolve CVE-2020-26139 to CVE-2020-26145, CVE-2020-24586 to CVE-2020-24588
2. Fixed a log-out mechanism for WUI in Internet Explorer

### **Known Issues**

(None)

|                   |  |
|-------------------|--|
| Firmware Version  | 1.3.3  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 23 <sup>rd</sup> March 2021                          |
| Build Date        | 3 <sup>rd</sup> February 2021                        |
| Revision          | g468_6d5f8c3   |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

1. Support for AP management (as a node)

### **Improvements**

1. 3DES ciphers disabled
2. WMM can be enabled or disabled in [Wireless LAN] > [Advanced Setting] section
3. Reset button can be enabled or disabled in [System Maintenance] > [Management] section
4. Improved the wireless network connection security
5. A note added "To allow communication between clients with different SSIDs on different bands..." on [Wireless LAN] > [General Setup] page
6. [Wireless LAN (5GHz)] > [Station List] did not display SSIDs properly
7. Resolved a display error issue of Wireless 5G Channel Load value on System Log
8. Under some conditions, the VigorAP could require wireless clients to enter a password when connecting to a wireless network configured with open access / no-password security
9. Unexpected message would appear when accessing [Wireless LAN (5GHz)] configuration page

### **Known Issues**

(None)

|                   |   |
|-------------------|---|
| Firmware Version  | 1.3.2   |
| Release Type      | <b>Critical</b> – Upgrade recommended immediately |
| Release Date      | 1 <sup>st</sup> April 2020                        |
| Build Date        | 26 <sup>th</sup> March 2020                       |
| Revision          | 11839   |
| Applicable Models | VigorAP 910C                                      |
| Locale            | UK Only   |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

(None)

### **Improvements**

1. Improved SNMP functionality
2. Improved WebGUI security

### **Known Issues**

(None)

|                   |  |
|-------------------|--|
| Firmware Version  | 1.3.1  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 5 <sup>th</sup> February 2020                        |
| Build Date        | 9 <sup>th</sup> January 2020                         |
| Revision          | 11412  |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

(None)

### **Improvements**

1. Renaming "Vigor Name" with "Device Name" in [Wireless LAN] > [Universal Repeater]
2. Vigor router APM compatibility updated
3. [Wireless LAN] > [Station List] window enlarged for the convenience of viewing device information
4. Improved mechanism of deleting individual MAC addresses from [Wireless LAN] > [Access Control]

### **Known Issues**

(None)

|                   |  |
|-------------------|--|
| Firmware Version  | 1.3.0  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 25 <sup>th</sup> October 2019                        |
| Build Date        | 9 <sup>th</sup> October 2019                         |
| Revision          | 11127  |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

1. [Device Object] added and integrated with WLAN access control & schedule
2. “Allow management from WLAN” option and Access List in [System Maintenance] > [Management] added
3. Support of Layer 2 member isolation added to [Object Settings] > [Device Object]
4. Logout button is now available on the dashboard

### **Improvements**

1. Improved layout of the [System Maintenance] > [Administration Password]

### **Known Issues**

1. If the menu displays "treeapp obj setting" after upgrading the firmware, refresh your browser cache or press Ctrl+F5 to resolve this

|                   |  |
|-------------------|--|
| Firmware Version  | 1.2.9  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 29 <sup>th</sup> July 2019                           |
| Build Date        | 18 <sup>th</sup> July 2019                           |
| Revision          | 10633  |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

(None)

### **Improvements**

1. Updates to TLS mechanism for compatibility with VigorACS 2.5.0

### **Known Issues**

1. The VigorAP will prompt to restart if the available memory is too low to perform the firmware upgrade. If firmware upgrade via web interface fails, restart the VigorAP and retry the update. Otherwise update the VigorAP through TFTP using the Firmware Upgrade Utility



|                   |  |
|-------------------|--|
| Firmware Version  | 1.2.8  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 17 <sup>th</sup> May 2019                            |
| Build Date        | 26 <sup>th</sup> March 2019                          |
| Revision          | 10090  |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

(None)

### **Improvements**

1. Details configured in [RADIUS] > [RADIUS Server] could be displayed incorrectly with entries over 20 characters in length, after clicking the OK button
2. Wireless clients now remain connected when making changes to the Access Control list in [Wireless LAN] > [Access Control]

### **Known Issues**

The VigorAP will prompt to restart if the available memory is too low to perform the firmware upgrade. If firmware upgrade via web interface fails, restart the VigorAP and retry the update. Otherwise update the VigorAP through TFTP using the Firmware Upgrade Utility

|                   |  |
|-------------------|--|
| Firmware Version  | 1.2.7  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 31 <sup>st</sup> October 2018                        |
| Build Date        | 16 <sup>th</sup> October 2018                        |
| Revision          | 9351   |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

(None)

### **Improvements**

1. Improved memory usage
2. Access Control for 5GHz WiFi only showed 64 entries when transferring WLAN Profile from APM ([Central Management] > [AP] > [WLAN Profile] on the router) with over 64 entries

### **Known Issues**

The VigorAP will prompt to restart if the available memory is too low to perform the firmware upgrade. If firmware upgrade via web interface fails, restart the VigorAP and retry the update. Otherwise update the VigorAP through TFTP using the Firmware Upgrade Utility

|                   |  |
|-------------------|--|
| Firmware Version  | 1.2.6  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 23 <sup>rd</sup> October 2018                        |
| Build Date        | 20 <sup>th</sup> September 2018                      |
| Revision          | 9231   |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

(None)

### **Improvements**

1. IGMP Snooping can now be enabled for the 5GHz WLAN interface from [Wireless LAN (5GHz)] > [Advanced Setting]
2. Time and Date configuration on the VigorAP now uses NTP Client as the factory default
3. WDS security key could not be saved for 2.4GHz WDS wireless configuration
4. Resolved an issue with the router intermittently losing APM connectivity with the VigorAP
5. Corrected an issue with the NTP client functionality of the VigorAP

### **Known Issues**

The VigorAP will prompt to restart if the available memory is too low to perform the firmware upgrade. If firmware upgrade via web interface fails, restart the VigorAP and retry the update. Otherwise update the VigorAP through TFTP using the Firmware Upgrade Utility

|                   |  |
|-------------------|--|
| Firmware Version  | 1.2.5  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 3 <sup>rd</sup> September 2018                       |
| Build Date        | 16 <sup>th</sup> August 2018                         |
| Revision          | 9032   |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

1. Support for transfer of Access Control List between VigorAPs using VigorACS

### **Improvements**

1. In some scenarios incorrect STUN / UDP connection data could be sent to the VigorACS server during registration

### **Known Issues**

If firmware upgrade via web interface fails, restart the VigorAP and retry the update. Otherwise update the VigorAP through TFTP using the Firmware Upgrade Utility

|                   |   |
|-------------------|---|
| Firmware Version  | 1.2.4   |
| Release Type      | <b>Critical</b> – Upgrade recommended immediately |
| Release Date      | 30 <sup>th</sup> May 2018                         |
| Build Date        | 7 <sup>th</sup> May 2018                          |
| Revision          | 8404  |
| Applicable Models | VigorAP 910C                                      |
| Locale            | UK Only   |

### **New Features**

1. 5GHz Wireless LAN now supports AP Bridge-WDS mode
2. Captive Web Portal facility added to [LAN] > [Web Portal]
3. Wireless Pre-Shared Key can now be viewed when logged into the VigorAP's web interface. Click on the "\*\*\*\*\*" text to reveal the password currently in use
4. Auto Channel Reselect now available in [Wireless LAN] > [Advanced Setting] – enabling this will have the VigorAP scan for and select a new channel to use; if the currently auto selected channel's detected utilisation / interference goes over 70% (refer to [Diagnostics] > [Interference Monitor] for an example)

### **Improvements**

1. This firmware includes improvements to harden the web interface against attacks
2. Increased the number of MAC address filter profiles in [Wireless LAN (5GHz)]>[Access Control] to 256 entries
3. The VigorAP can now be reflashed back to factory default settings by renaming a VigorAP ".all" firmware to ".rst" extension and sending that to the VigorAP
4. When configuring RADIUS 802.1X authentication in EAP TLS mode, the VigorAP will now require creation of a root CA in [RADIUS Setting] > [Certificate Management] before proceeding
5. Recommended wireless channel was not displayed when scanning channel usage [Diagnostics] > [Interference Monitor]
6. The VigorAP would not allow configuration of a WLAN Trusted DHCP Server IP address ending in "xxx.xxx.xxx.0"
7. VigorACS 2 was unable to configure AP Assisted Client Roaming
8. VigorAP did not send Root CA certificate if PEAP was selected as RADIUS EAP Type
9. If Channels 36-48 were specified as filtered out channels for Auto channel usage, the Active Channel could under some circumstances display channel 36 being used in [Wireless LAN 5GHz] > [General Setup]
10. Vendor information for some Apple devices was not displayed correctly in [Mobile Device Management] > [Detection]
11. Product registration page could not work if accessing web user interface through HTTPS
12. VigorACS 2 Dashboard was unable to display the full 5GHz wireless client list in some situations

|                   |  |
|-------------------|--|
| Firmware Version  | 1.2.3.2  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 5 <sup>th</sup> January 2018                         |
| Build Date        | 1 <sup>st</sup> December 2017                        |
| Revision          | 7833   |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

1. EAPOL Key Retry Enable/Disable setting added to [Wireless LAN (2.4GHz/5GHz)] > [Security]  
Disabling this setting can prevent WPA2 Key Reinstallation Attack (KRACK) attack vectors, for more details please read this security advisory:  
<https://www.draytek.co.uk/information/our-technology/wpa2-krack-vulnerability>  
(EAPOL Key Retry is set to Enabled by default and in previous firmware)

### **Improvements**

(None)

### **Known Issues**

If firmware upgrade via web interface fails, restart the VigorAP and retry the update. Otherwise update the VigorAP through TFTP using the Firmware Upgrade Utility



|                   |  |
|-------------------|--|
| Firmware Version  | 1.2.3.1  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 20 <sup>th</sup> October 2017                        |
| Build Date        | 20 <sup>th</sup> October 2017                        |
| Revision          | 7660   |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

1. Isolation between SSIDs and Bands (2.4GHz <-> 5Ghz) can now be enabled or disabled from [Wireless LAN] > [Advanced Setting]
2. Setting for 'Isolate Member with IP' added to [Wireless LAN] > [Advanced Setting] to control the behaviour of [Wireless LAN] > [General] > Isolate Member  
Enabled – Block ARP packets from WLAN clients if isolate member set for SSID  
Disabled –Allow ARP packets from WLAN clients if isolate member set for SSID  
The advantage of 'enabled' behaviour is that clients will be blocked from using the LAN gateway as a proxy via which to communicate with other LAN clients
3. Support for extra TR-069 parameters
4. TLS 1.2 support added to TR-069 client

### **Improvements**

1. Improvements to Universal Repeater mode WPA2 security to protect against WPA2 Key Reinstallation Attack (KRACK), for more details please read this security advisory: <https://www.draytek.co.uk/information/our-technology/wpa2-krack-vulnerability>
2. Central AP Management via Vigor 2952 and Vigor 3220 could not retrieve station list data
3. Support for compression of Central AP Management (via router) data to improve management across remote links
4. Corrected an issue with AP-assisted Client Mobility when using Minimum RSSI mode
5. SSID names now allow spaces and these special characters (@ # \$ % \* \_ - .)
6. Central AP Management did not configure optimal settings for 11ac wireless clients when provisioning the VigorAP with the "Default" profile

### **Known Issues**

If firmware upgrade via web interface fails, restart the VigorAP and retry the update. Otherwise update the VigorAP through TFTP using the Firmware Upgrade Utility





|                   |  |
|-------------------|--|
| Firmware Version  | 1.2.3  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Release Date      | 5 <sup>th</sup> September 2017                       |
| Build Date        | 5 <sup>th</sup> September 2017                       |
| Revision          | 7562   |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

1. Support for extra TR-069 parameters

### **Improvements**

1. Support for configuration of Channel Width and other parameters through Central AP Management
2. Improvements to [TR-069] configuration page with URL Wizard, TR-069 status information and “Test With Inform” button to test TR-069 connectivity when pressed
3. Improvements to memory handling
4. Minor improvements to the AP Discovery and Data Flow Monitor pages
5. Communication between wireless clients on 2.4GHz and 5GHz SSIDs is now allowed where the SSID is the same for both wireless bands

### **Known Issues**

1. If firmware upgrade via web interface fails, restart the VigorAP and retry the update. Otherwise update the VigorAP through TFTP using the Firmware Upgrade Utility
2. Interoperability issue with some VigorACS servers when connecting via HTTPS. This is fixed in 1.2.3.1 firmware

|                   |  |
|-------------------|--|
| Firmware Version  | 1.2.1  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient<br>Note: The previous firmware (1.2.0) was a <b>critical release</b> . This f/w includes all changes/improvements that were in 1.2.0. |
| Release Date      | 27 <sup>th</sup> July 2017   |
| Build Date        | 30 <sup>th</sup> June 2017   |
| Revision          | 7322   |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

If upgrading from firmware version 1.2.0, reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

1. Support for extra TR-069 parameters
2. Added mechanism to check connectivity to specified IP Address / Hostname and disable Wi-Fi if it is unavailable, in [Applications] > [Wi-Fi Auto On/Off]
3. Added 5GHz SSID Isolation support

### **Improvements**

1. Improvements to interface and functionality of web firmware upgrade process
2. Added TR-069 parameters for wireless traffic statistics
3. Improvements to functionality and layout of [System Maintenance] > [Configuration Backup]
4. 5GHz WLAN Transmit Power setting can now be configured through Central AP Management
5. Configuring Universal Repeater for 5GHz through Quick Start Wizard did not update SSID & Channel parameters when selecting from AP Discovery search results
6. Resolved a [Data Flow Monitor] display issue
7. Corrected a problem that could occur with Central AP Management when using WPA2/802.1x Security Mode on the VigorAP 910C
8. Updated Wireless Driver
9. Schedule system can now apply schedules overnight in a single schedule entry

### **Known Issues**

If firmware upgrade via web interface fails, restart the VigorAP and retry the update. Otherwise update the VigorAP through TFTP using the Firmware Upgrade Utility

|                   |  |
|-------------------|--|
| Firmware Version  | 1.2.0.1  |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient<br>Note: The previous firmware (1.2.0) was a <b>critical release</b> . This f/w includes all changes/improvements that were in 1.2.0. |
| Release Date      | 12 <sup>th</sup> April 2017  |
| Build Date        | 3 <sup>rd</sup> March 2017   |
| Revision          | 6852   |
| Applicable Models | VigorAP 910C   |
| Locale            | UK Only  |

### **Important Note**

Please reboot (power cycle or software reboot) the VigorAP 910C before commencing the firmware upgrade process

### **New Features**

1. The VigorAP's configured name is now displayed in the page / tab title of the browser
2. [Diagnostics] > [Data Flow Monitor] now displays total throughput values

### **Improvements**

1. Resolved an issue with Internet access for SSIDs with VLAN tag and Isolate Member enabled
2. [Central AP Management] > [APM Log] would not clear correctly when using Clear option
3. AP Discovery on 2.4GHz band did not display results correctly after clicking Scan
4. Improved interoperability of "Isolate Member" function with some wireless clients
5. Configuring Universal Repeater for 5GHz through Quick Start Wizard did not update SSID & Channel parameters when selecting from AP Discovery search results
6. Device Name was limited to 15 characters only, now allows up to 31 characters
7. Performing a Speed Test could stop the web interface from responding
8. Resolved an issue with changing Channel Width setting for 5GHz band in Advanced Settings
9. Some Wireless specific settings moved from [WLAN] > [General Setup] to [WLAN] > [Advanced Setting]

### **Known Issues**

If firmware upgrade via web interface fails, restart the VigorAP and retry the update. Otherwise update the VigorAP through TFTP using the Firmware Upgrade Utility



|                   |   |
|-------------------|---|
| Firmware Version  | 1.2.0   |
| Release Type      | <b>Critical</b> – Upgrade recommended immediately |
| Release Date      | 19 <sup>th</sup> January 2017                     |
| Build Date        | 12 <sup>th</sup> December 2016                    |
| Revision          | 6649  |
| Applicable Models | VigorAP 910C                                      |
| Locale            | UK Only   |

### **New Features**

1. The number of clients allowed to connect can be limited per SSID
2. The AP can be configured to disable its wireless interface while its Internet connection is unavailable, determined with ping detection, in [Applications] > [Auto Switch On/Off Wi-Fi]
3. SNMP support added via SNMPv3
4. The AP's Telnet interface can be disabled from [System Maintenance] > [Management]
5. If the AP's DHCP server is disabled, the AP can now be configured to allow only a Trusted DHCP server IP to provide DHCP to wireless clients under [LAN] > [General Setup]

### **Improvements**

1. Security improvements including one or more considered critical.
2. Improvements to the Quick Start Wizard
3. The Isolate Member function did not work for wireless LAN clients in some scenarios
4. Advanced wireless settings such as MAC Clone, TX Power % moved to [Wireless LAN] > [Advanced Settings]
5. Auto channel selection now has **Auto Channel Filtered Out List** to specify which channels should not be used by the AP when auto detecting which wireless channel to operate on
6. [Wireless LAN] > [Station List] now displays Vendor name derived from MAC address OUI
7. Improvements to Fast Handoff using WPA2/802.1x security

### **Known Issues**

(None)

|                   |                  |
|-------------------|------------------|
| Firmware Version  | 1.1.7.2          |
| Release Date      | 7th October 2016 |
| Applicable Models | VigorAP 910C     |
| Locale            | UK ONLY          |

### **New Features**

(None)

### **Improvement**

1. ACS required two attempts to successfully write settings to AP immediately after AP reboot
2. Resolved an issue that stopped Windows 10 computers from reconnecting to a VigorAP when using WPA2/802.1x security and the EAP-TLS RADIUS functionality on the AP
3. Universal Repeater 5GHz mode could not connect to the remote wireless network if the pass-phrase contained ";" (semicolon) character
4. Improved HTTPS response times for VigorAP web interface
5. Added VigorACS TR-069 parameters for Airtime Fairness and Wireless LAN Client Limit

### **Known Issues**

(None)

|                   |                |
|-------------------|----------------|
| Firmware Version  | 1.1.7          |
| Release Date      | 23rd June 2016 |
| Applicable Models | VigorAP 910C   |
| Locale            | UK ONLY        |

### **New Features**

1. Mobile Device Management added to control connections to the AP from mobile devices, PCs / Laptops and unknown devices
2. [Wireless LAN] > [Roaming] has new AP-assisted Client Roaming options to disassociate clients based on RSSI (recommended) or data rate
3. RTS Threshold and Fragment Length and Wireless Region can be configured from [Wireless LAN] > [Advanced Setting]
4. Support additional TR-069 related parameters for central AP management
5. [Wireless LAN] > [Station List] > [Neighbour] now shows Vendor names
6. The configuration backup can now be password protected & encrypted
7. Mail Alert can now send via TLS, configured under [System Maintenance] > [Syslog / Mail Alert Setup]

### **Improvement**

1. Session validation method improved in Web UI
2. Universal Repeater mode can now pass Airplay / mDNS packets across the wireless link
3. Resolved an issue that could stop an AP using RADIUS / 802.1X authentication from passing traffic after changing 5GHz security settings
4. Resolved LAN port issue that could occur when using Schedules
5. Enabling Management VLAN could stop NTP from updating
6. Resolved display/functionality issues in [Wireless LAN 5GHz] > [Bandwidth Management]
7. Add legend ("Seconds") for "Session Timeout" field in RADIUS Server settings under [Wireless LAN] > [Security]
8. Improvements to Band Steering mechanism
9. The web interface now displays a notification to change the default password of the AP
10. Performance improvements to 5GHz Airtime Fairness
11. [Central AP Management] > [Status of Settings] updated with RSSI Threshold
12. Improved connection speed with 5GHz WPA2/PSK and 2.4GHz WPA2/802.1x connections

### **Known Issues**

(None)



|                   |                    |
|-------------------|--------------------|
| Firmware Version  | 1.1.6              |
| Release Date      | 22nd February 2016 |
| Applicable Models | VigorAP 910C       |
| Locale            | UK ONLY            |

### **New Features**

1. Support for 5GHz PMK Caching under [Wireless LAN (5GHz)] > [Roaming]
2. Band Steering added (requires same SSID & PSK on both 2.4GHz & 5GHz), to help 5GHz capable clients connect to the faster 5GHz band
3. Support for Air-time Fairness, enabled under [Wireless LAN]>[Airtime Fairness] - <http://www.draytek.co.uk/support/guides/kb-airtimefairness>
4. [Wireless LAN]>[Station Control] to automatically disconnect clients after a specified time period
5. Schedule to enable or disable wireless now supports controlling 2.4GHz or 5GHz (Radio), SSID 2, SSID 3 and SSID 4 in a schedule entry
6. Certificate Management added to [RADIUS Setting] menu, to generate a custom self-signed certificate for RADIUS server or WUI usage
7. [System Maintenance] > [Management] - LED Setup can now set the ACT LED to Blue, Orange or Purple. The LED can also be configured to remain "Always On" instead of "Flashing"
8. Added MAC address blacklist / whitelist to [Central AP Management] > [Overload Management]
9. [Diagnostics] > [WLAN (2.4GHz / 5GHz) Statistics] added to show detailed wireless statistics for the AP and per SSID
10. [Diagnostics] > [Station Statistics] added to display number of wireless clients nearby and connected to the AP on an hourly, daily or weekly basis
11. [Diagnostics] > [Data Flow Monitor] added to show bandwidth usage per wireless client
12. [Central AP Management] > [Status of Settings] added to indicate settings configured by the managing router

### **Improvement**

1. Unique self-signed certificate automatically generated on initial boot
2. RTS Threshold and Fragment Length can be configured from [Wireless LAN] > [Advanced Setting]

### **Known Issues**

(None)

|                   |                   |
|-------------------|-------------------|
| Firmware Version  | 1.1.5.2           |
| Release Date      | 27th October 2015 |
| Applicable Models | VigorAP 910C      |
| Locale            | UK ONLY           |

### **New Features**

1. The LED can be disabled permanently on the AP by setting the LED Status to Disable under [System Maintenance] > [Management] - LED Setup

### **Improvement**

1. Improvements to the bootloader to resolve an issue that would stop the ACT LED from working when updating to 1.1.5.1 firmware
2. LED Enable/Disable via schedule can be configured in the schedule options

### **Known Issues**

(None)

|                   |                     |
|-------------------|---------------------|
| Firmware Version  | 1.1.5.1             |
| Release Date      | 15th September 2015 |
| Applicable Models | VigorAP 910C        |
| Locale            | UK ONLY             |

### **New Features**

1. Support for Dynamic Frequency Selection on 5GHz wireless interface, allows use of channels 52-64 and 100-140

### **Improvement**

1. The Device Name configured for the AP now shows on the [System Maintenance] > [System Status] page
2. The AP will show a warning if the HTTP / HTTPS ports are changed on the AP
3. CPE Username and Password settings were not available when modifying settings via TR-069 / VigorACS
4. When the AP is in Universal Repeater mode, the Channel Autoselect option is no longer available, so that Universal Repeater mode can operate correctly
5. Resolved a display issue with [AP Discovery] which could occur after configuring the AP via the Quick Start Wizard
6. TR-069 parameters added to allow VigorACS to perform Central AP Management
7. Resolved a display issue with the Traffic Graph that would display inconsistent information for the Daily and Weekly views
8. Added a notification for AP Bridge - Point to Multi-Point mode under [Wireless LAN] > [General Setup] to indicate that Index 1 must be entered before Index 2
9. Resolved a display issue in [Wireless LAN (2.4GHz/5GHz)] > [Station List] that would display an incorrect Rx Rate value

### **Known Issues**

1. The option to disable LED via schedule is unavailable. Disable/Enable LED schedule entries configured in 1.1.5 will continue to work with 1.1.5.1 firmware

|                   |                     |
|-------------------|---------------------|
| Firmware Version  | 1.1.5               |
| Release Date      | 11th September 2015 |
| Applicable Models | VigorAP 910C        |
| Locale            | UK ONLY             |

### **New Features**

1. 5GHz Universal Repeater Mode
2. 5GHz Bandwidth Management
3. Support for Central AP Management
4. "Where Am I?" Buzzer feature, can be triggered manually or via schedule

### **Improvement**

(None)

|                   |                         |
|-------------------|-------------------------|
| Firmware Version  | 1.1.3.2 (first release) |
| Applicable Models | VigorAP 910C            |
| Locale            | UK ONLY                 |

**First Firmware Release for this model**

**[END OF FILE]**