

Release Notes for DrayTek VigorSwitch P2261 (UK/Ireland)

Firmware Version	3.35 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	10 th January 2017
Release Date	6 th March 2017
Applicable Models	VigorSwitch P2261
Locale	UK & Ireland Only

New Features

1. LLDP is now enabled by default
2. PoE power consumption can now be viewed per port in graph format from [Configuration] > [PoE] > [Report] by selecting a port and time range

Improvements

1. When a user without Single IP Management privilege logs into a Master switch, the Single IP group links are no longer displayed
2. Settings configured in Access Control List were not included in an exported configuration file
3. Management Username and Password settings are no longer included in exported configuration files
4. Resolved an issue that could cause high CPU load when using sFlow
5. Resolved display issue in Single IP Information Help menu

Known Issues

(None)

Firmware Version	3.18
Release Date	19th May 2016
Applicable Models	VigorSwitch P2261
Locale	UK ONLY

New Features

(None)

Improvement

1. Improved HTTPS management to resolve compatibility issues with Firefox browser
2. Improved sFlow functionality

Firmware Version	3.11
Release Date	4th September 2015
Applicable Models	VigorSwitch P2261
Locale	UK ONLY

New Features

(None)

Improvement

1. The External Device Auto Discovery feature on DrayTek routers could cause a reboot of the VigorSwitch with some configurations
2. Resolved a configuration import issue that could stop the SFP ports from establishing a connection

Firmware Version	2.91
Release Date	1st April 2015
Applicable Models	VigorSwitch P2261
Locale	UK ONLY

New Features

(None)

Improvement

1. Resolved an interoperability issue with Wyrestorm Matrix products
2. Resolved a problem with port settings when exporting and importing the switch configuration

Firmware Version	2.04
Release Date	22nd April 2013
Applicable Models	VigorSwitch P2261
Locale	UK ONLY

New Features

(None)

Improvement

1. Resolved a display issue when using Single IP Management

Firmware Version	1.44 (first release)
Applicable Models	VigorSwitch P2261
Locale	UK ONLY

First Firmware Release

[END OF FILE]