Release Notes for DrayTek VigorAP 912c (UK/Ireland)

| Firmware Version | 1.4.0 |
|-------------------|---|
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 23 rd March 2021 |
| Build Date | 3 rd February 2021 |
| Revision | g470_81a80a4fd8 |
| Applicable Models | VigorAP 912c |
| Locale | UK Only |

New Features

- 1. Hotspot Web Portal feature can be activated on [LAN] > [Hotspot Web Portal]
- Manage up to 20 VigorAP access points by enabling "RootAP" mode from [Central AP Management] > [General Setup]

Improvements

- 1. Updated MyVigor authentication method
- 2. Last Sync update time information added on [Mesh] > [Mesh Setup] page
- 3. Disabling WMM in [Wireless LAN] > [Advanced Setting] will display a warning: 'To allow the maximum 802.11n rates, ensure that WMM Capable is enabled'
- 4. Improved Mesh Preferred Uplink timeout option [Mesh] > [Mesh Setup]
- 5. Port 9608 TCP is now closed when Mesh Root / Root AP mode is disabled
- 6. Mail alerts could not be sent through smtp.gmail.com
- 7. Improved image display on Quick Start Wizard page
- 8. Vigor routers External Devices list did not update HTTP port number if not 80
- 9. In some conditions, 2.4GHz clients could not connect to the AP after a few days with AP-Assisted Roaming enabled

| K | n | o | w | n | Iss | u | es |
|---|---|---|---|---|-----|---|----|
|---|---|---|---|---|-----|---|----|

| (N | lo | n | e) |
|----|----|---|----|
|----|----|---|----|

Firmware File Types

The file name of the firmware controls which upgrade type is performed. If the file name is unchanged (e.g. xxxx.all) then the upgrade will just upgrade the firmware, whereas renaming the firmware to a .rst extension will wipe all settings back to factory defaults when upgrading the firmware.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the AP's system maintenance menu.

To upgrade firmware, select 'firmware upgrade' from the AP's system maintenance menu and select the correct file. The access point will perform the upgrade and automatically reboot once this completes.



Manual Upgrade

If you cannot access the AP's menu, you can put the AP into 'TFTP' mode by holding the FACTORY RESET button whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier.

| Firmware Version | 1.3.5 |
|-------------------|---|
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 21 st September 2020 |
| Build Date | 19 th August 2020 |
| Revision | 12591 |
| Applicable Models | VigorAP 912c |
| Locale | UK Only |

1. Support for TLS 1.3 Encryption on [System Maintenance] > [Management]

Improvements

- 1. Improved compatibility and stability for Mesh networks
- 2. [Mobile Device Management] > [Station Nearby] vendor information updated
- 3. Mesh Nodes can now have their preferred next 'hop' specified as the "Preferred Uplink" on the [Mesh] > [Mesh Setup] page of an AP operating as a Mesh Node
- 4. Updated wireless chipset drivers to resolve CVE-2019-15126 and CVE-2020-3702
- 5. Disabling 5GHz while AP is running as Mesh Root will now display a warning message
- 6. A note added about the traffic being allowed between 2.4 and 5G bands. Settings can be adjusted in [Wireless LAN] > [Advanced Settings] section
- 7. VigorAP's Reset button can now be disabled in [System Maintenance] > [Management]
- 8. Improvements to [Mesh] > [Basic Configuration Sync / Advanced Configuration Sync] pages
- 9. Updated naming used for wireless security options to Personal (PSK) and Enterprise (802.1x)
- 10. In some specific conditions, wireless clients connected to the AP in Range Extender mode could not obtain an IP from DHCP server/router
- 11. Resolved display issue for Operation Mode on [Quick Start Wizard] page
- 12. Special characters such as '- ' can now be used with Mesh Root administrator password
- 13. Resolved wireless channel display issue on [Wireless LAN] > [General Setup] page
- 14. Improved SNMP functionality

Known Issues

| Firmware Version | 1.3.4.1 |
|-------------------|---|
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 24 th April 2020 |
| Build Date | 20 th April 2020 |
| Revision | 11968 |
| Applicable Models | VigorAP 912c |
| Locale | UK Only |

(None)

Improvements

1. [Diagnostics] > [System Log] page would not open

Known Issues

| Firmware Version | 1.3.4 |
|-------------------|--|
| Release Type | Critical – Upgrade recommended immediately |
| Release Date | 1 st April 2020 |
| Build Date | 27 th March 2020 |
| Revision | 11841 |
| Applicable Models | VigorAP 912c |
| Locale | UK Only |

(None)

Improvements

- 1. Improved SNMP functionality
- 2. Improved WebGUI security

Known Issues

| Firmware Version | 1.3.3 |
|-------------------|---|
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 31 st March 2020 |
| Build Date | 6 th March 2020 |
| Revision | 11701 |
| Applicable Models | VigorAP 912c |
| Locale | UK Only |

- Add the options of Access List and Allow management from WLAN on [System Maintenance] > [Management]
- 2. Add the option for enabling / disabling TLS/SSL Encryption Setup on [System Maintenance] > [Management]

Improvements

- 1. [Wireless LAN] > [Station List] window enlarged for the convenience of viewing device information
- 2. Change the colour of the index number on [Application] > [Schedule]
- 3. Mesh network stability improvements
- 4. Improvements to DHCP Server

Known Issues

| Firmware Version | 1.3.2 (Formal Release) |
|-------------------|-------------------------------|
| Release Type | Initial Release |
| Release Date | 30 th January 2020 |
| Build Date | 7 th January 2020 |
| Revision | 11442 |
| Applicable Models | VigorAP 912c |
| Locale | UK Only |

First Firmware Release for this model

Known Issues

(None)

[END OF FILE]