Release Notes for DrayTek VigorSwitch P1092 (UK/Ireland)

Firmware Version	1.04.07 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	6 th March 2019
Build Date	25 th January 2019
Applicable Models	VigorSwitch P1092
Locale	UK & Ireland Only

New Features

Port Isolation – to control forwarding of packets between ports for broadcast control.
Enable on at least 2 ports to activate. Isolated ports can communicate with normal ports, but cannot communicate with other isolated ports.

Improvements

- 1. Improvements to Link Aggregation functionality
- 2. Improvements to Port Loop Prevention algorithm
- 3. Improved handling of Switch Management communication data between Vigor router and VigorSwitch

Important Note - Requirements to update Port Loop Prevention algorithm

To take advantage of the improved Loop Prevention algorithm, it is necessary to factory reset the VigorSwitch after updating to the 1.04.07 firmware. This step is optional; without a reset the switch will function normally but won't offer the updated port loop prevention algorithm.

It is possible to use the existing configuration and make use of the improvements to Loop Protection by performing the following steps:

- 1. Take a configuration backup from the 1.04.06 firmware. Go to [System Maintenance] > Device Configuration and click **Backup** to download the configuration file.
- 2. Upgrade the VigorSwitch to 1.04.07 firmware
- 3. Factory Reset the VigorSwitch from [System Maintenance] > Reboot or Reset > **Reset**
- 4. Reload the saved configuration file from [System Maintenance] > Device Configuration. Select the saved "switch_cfg.bin" file and click **Restore**

Known Issues

Firmware Version	1.04.06 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	22 nd October 2018
Build Date	2 nd October 2018
Applicable Models	VigorSwitch P1092
Locale	UK & Ireland Only

1. LAN ports can now be disabled through the switch web interface in [Port Statistics] with the Port State setting

Improvements

- 1. Gateway address can now be specified with the switch IP configuration in Static mode
- 2. The Direction setting of [Port Mirroring] could not be set to "Both" directions

Known Issues

Firmware Version	1.04.05 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	10 th July 2018
Build Date	6 th June 2018
Applicable Models	VigorSwitch P1092
Locale	UK & Ireland Only

1. DrayTek Switch Management Support added

Improvements

1. Up to 10 VLAN groups can now be configured on the VigorSwitch P1092

Known Issues

Firmware Version	1.04.04 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	17 th May 2018
Applicable Models	VigorSwitch P1092
Locale	UK & Ireland Only

1. MAC Table added

Improvements

1. The VLAN group will be shown in green if it is tagged

Known Issues

Firmware Version	1.04.02 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	
Applicable Models	VigorSwitch P1092
Locale	UK & Ireland Only

(None)

Improvements

- 1. Menu layout modified Logout and Reboot icons now located in upper right of web interface
- 2. Added Help menu section

Known Issues

Firmware Version	1.01.03 (Formal Release)
Release Type	First Firmware Release
Build Date	1 st August 2017
Release Date	15 th January 2018
Applicable Models	VigorSwitch P1092
Locale	UK & Ireland Only

First Firmware Release

[END OF FILE]