# Release Notes for DrayTek VigorSwitch G2540x (UK/Ireland)

| | |
|---|---|
| Firmware Version | 2.9.5 (Formal Release) |
| Release Type | **Regular** – Upgrade recommended when convenient |
| Build Date | 15th July 2024 |
| Release Date | 15th November 2024 |
| Build Revision | ef29dcb |
| Applicable Models | VigorSwitch G2540x |
| Locale | UK & Ireland Only |

## New Features

(none)

## Improvements

1. Improvements to the TR-069 parameter related issues
2. The CPU usage mechanism improvements
3. Fix an issue related to the IP Source Guard and DHCP snooping used simultaneously

## Known Issues

(none)

| Firmware Version | 2.9.4 (Formal Release) |
|---|---|
| Release Type | **Regular** – Upgrade recommended when convenient |
| Build Date | 29th April 2024 |
| Release Date | 4th November 2024 |
| Build Revision | 24df0f6 |
| Applicable Models | VigorSwitch G2540x |
| Locale | UK & Ireland Only |

## New Features

(none)

## Improvements

1. Password mechanism changed to force admin to change the password from the default password
2. The ICP table size increased to 1024
3. Port Description added on the Bandwidth Utilization page
4. The configuration process for LAG has been updated
5. The firmware release notifications mechanism added
6. The syslog display time adjustments related to the daylight-saving time
7. The SFP+ port information can be displayed on the dashboard
8. The management port configuration option improvements
9. The device MAC address details included in syslog

## Known Issues

(none)

| Firmware Version | 2.7.4 (Formal Release) |
|---|---|
| Release Type | **Regular** – Upgrade recommended when convenient |
| Build Date | 07th July 2022 |
| Release Date | 05th August 2022 |
| Build Revision | 023db45 |
| Applicable Models | VigorSwitch G2540x |
| Locale | UK & Ireland Only |

## New Features

1. The function of Dying gasp added allowing the switch to indicate the power-related downtime
2. Added the new algorithm (IP only or Source Port only) for LAG
3. Support for 10Gigabit Ethernet port auto linkup added

## Improvements

1. 10G ports set with link aggregation did not working after device reboot
2. Updated HTTPS mechanism to address the CVE-2022-0778 (OpenSSL)
3. The fibre ports media type default setting is set to Auto
4. Port Bandwidth Utilization page's colours match the Dashboard
5. The RADIUS settings disappeared after restarting the switch
6. The status information of the SFP optical module improvements
7. The VLAN interface uplink TPID setting could not be stored by the switch

| Firmware Version | 2.6.7 (Formal Release) |
|---|---|
| Release Type | **Regular** – Upgrade recommended when convenient |
| Build Date | 26th January 2021 |
| Release Date | 25th August 2021 |
| Build Revision | 1959 |
| Applicable Models | VigorSwitch G2540x |
| Locale | UK & Ireland Only |

## New Features

(none)

## Improvements

1. Updated MyVigor authentication method

| Firmware Version | 2.6.4 (Formal Release) |
|---|---|
| Release Type | **First Firmware Release** |
| Build Date | 4th August 2020 |
| Release Date | 1st February 2021 |
| Build Revision | 1916 |
| Applicable Models | VigorSwitch G2540x |
| Locale | UK & Ireland Only |

**First Firmware Release**

**[END OF FILE]**