Release Notes for DrayTek VigorAP 960c (UK/Ireland)

Firmware Version	1.3.9 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	3 rd February 2021
Build Date	7 th December 2020
Revision	g346_5a3e053934
Applicable Models	VigorAP 960c
Locale	UK Only

New Features

- 1. Added VigorAP Hotspot Web Portal
- 2. Added VigorAP Central Management

Improvements

- 1. Improvements to Mesh transfer throughput
- 2. In some specific conditions, clients could not connect to 2.4GHz band with Roaming enabled
- 3. Corrected HTTP port number displayed in [External Devices] information

Known Issues

(None)

Firmware File Types

The file name of the firmware controls which upgrade type is performed. If the file name is unchanged (e.g. *xxxx*.**all**) then the upgrade will just upgrade the firmware, whereas renaming the firmware to a .**rst** extension will wipe all settings back to factory defaults when upgrading the firmware.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the AP's system maintenance menu.

To upgrade firmware, select 'firmware upgrade' from the AP's system maintenance menu and select the correct file. The access point will perform the upgrade and automatically reboot once this completes.



Manual Upgrade

If you cannot access the AP's menu, you can put the AP into 'TFTP' mode by holding the FACTORY RESET button whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier.

Firmware Version	1.3.8 (Formal Release)
Release Type	Initial Release
Release Date	27 th August 2020
Build Date	27 th August 2020
Revision	12627
Applicable Models	VigorAP 960c
Locale	UK Only

First Firmware Release for this model

Known Issues

(None)

[END OF FILE]