

Release Notes for DrayTek VigorAP 960c (UK/Ireland)

Firmware Version	1.4.9 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	28th August 2024
Build Date	14 th June 2024
Revision	g1715_c606078d61
Applicable Models	VigorAP 960c
Locale	UK Only

New Features

(None)

Improvements

1. Password mechanism changed to force admin to change the password from the default password
2. Client statistics could not be displayed via VigorACS
3. Some wireless clients would get other LAN's RA in SLAAC IPv6 environment
4. The Auto Channel Filtered Out List option on [Wireless LAN] > [Advanced Setting] failed to work

Known Issues

(None)


Firmware File Types

The file name of the firmware controls which upgrade type is performed. If the file name is unchanged (e.g. xxxx.all) then the upgrade will just upgrade the firmware, whereas renaming the firmware to a .rst extension will wipe all settings back to factory defaults when upgrading the firmware.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the AP's system maintenance menu.

To upgrade firmware, select '*firmware upgrade*' from the AP's system maintenance menu and select the correct file. The access point will perform the upgrade and automatically reboot once this completes.



Manual Upgrade

If you cannot access the AP's menu, you can put the AP into 'TFTP' mode by holding the FACTORY RESET button whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier.

Firmware Version	1.4.8 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	9 th January 2024
Build Date	1 st December 2023
Revision	g1682_6b9d67b197
Applicable Models	VigorAP 960c
Locale	UK Only

New Features

(None)

Improvements

1. Improvements to the roaming features
2. Fix for the compatibility with VigorACS platform
3. VigorAP could not be accessed from the Internet
4. SSID did not broadcast when Fast Transition Roaming 802.11r was enabled

Known Issues

(None)

Firmware Version	1.4.7 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	11 th April 2023
Build Date	23 rd February 2023
Revision	g1568_f57251d5de
Applicable Models	VigorAP 960c
Locale	UK Only

New Features

1. Event Alert feature added into [**Diagnostics**] > [**Alert Event**]
2. WLAN security supports WPA2 PPSK mode

Improvements

1. Improvements to the web GUI (CVE-2019-16645)
2. Web access via HTTPS didn't work well after the firmware upgrade

Known Issues

(None)

Firmware Version	1.4.5 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	2 nd September 2022
Build Date	5 th August 2022
Revision	g1460_09cc32292e
Applicable Models	VigorAP 960c
Locale	UK Only

New Features

(None)

Improvements

1. Vigor router's Central AP Management could fail with VigorAP 960C access points after upgrading to 1.4.4 firmware

Known Issues

(None)

Firmware Version	1.4.4 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	30 th June 2022
Build Date	06 th May 2022
Revision	g1405_88af2ade15
Applicable Models	VigorAP 960c
Locale	UK Only

New Features

(None)

Improvements

1. Updated HTTPS mechanism to address the CVE-2022-0778 (OpenSSL)
2. Wireless clients connected to different SSIDs on the same radio band could not communicate with each other

Known Issues

(None)

Firmware Version	1.4.3 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	02 nd December 2021
Build Date	08 th November 2021
Revision	g1094_6c65efb432
Applicable Models	VigorAP 960c
Locale	UK Only

New Features

(None)

Improvements

1. Improve the WebGUI security
2. [Wireless LAN] > [Station List] and [Dashboard] could not correctly display statistics for throughput or number of clients connected

Known Issues

(None)

Firmware Version	1.4.2 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	11 th August 2021
Build Date	29 th June 2021
Revision	g608_37e534907b
Applicable Models	VigorAP 960c
Locale	UK Only

New Features

(None)

Improvements

1. Updated wireless chipset drivers to resolve CVE-2020-26139 to CVE-2020-26145, CVE-2020-24586 to CVE-2020-24588

Known Issues

(None)

Firmware Version	1.4.0 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	16 th April 2021
Build Date	03 rd February 2021
Revision	g470_81a80a4fd8
Applicable Models	VigorAP 960c
Locale	UK Only

New Features

(None)

Improvements

1. Updated MyVigor authentication method
2. Updated the MAC OUI database
3. Fixed the configuration backup mechanism

Known Issues

(None)

Firmware Version	1.3.9 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Release Date	3 rd February 2021
Build Date	7 th December 2020
Revision	g346_5a3e053934
Applicable Models	VigorAP 960c
Locale	UK Only

New Features

1. Added VigorAP Hotspot Web Portal
2. Added VigorAP Central Management

Improvements

1. Improvements to Mesh transfer throughput
2. In some specific conditions, clients could not connect to 2.4GHz band with Roaming enabled
3. Corrected HTTP port number displayed in [External Devices] information

Known Issues

(None)

Firmware Version	1.3.8 (Formal Release)
Release Type	Initial Release
Release Date	27 th August 2020
Build Date	27 th August 2020
Revision	12627
Applicable Models	VigorAP 960c
Locale	UK Only

First Firmware Release for this model

Known Issues

(None)

[END OF FILE]