# Release Notes for DrayTek VigorSwitch P2280x (UK/Ireland)

Firmware Version	2.8.4 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	9 <sup>th</sup> March 2023
Release Date	24 <sup>th</sup> April 2023
Build Revision	c013d8e
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

#### **New Features**

(none)

#### **Improvements**

- 1. Web User Interface improvements.
- 2. Fun speed controller improvements

#### Known Issues

- 1. It is not possible to downgrade the switch using 2.7.x or older firmware if the loader version is 3.5.1
- 2. The fans may not work at full speed on the new P2280x when using firmware 2.8.2. Please do not downgrade the firmware to 2.8.2 if the switch's original version is 2.8.4

Firmware Version	2.8.2 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	23 <sup>rd</sup> November 2022
Release Date	19 <sup>th</sup> December 2022
Build Revision	02c1dfd
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

(none)

- 1. Management ports of the switch can now be amended in GUI for HTTP/HTTPS/telnet
- 2. New PoE chip driver

Firmware Version	2.7.4 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	07 <sup>th</sup> July 2022
Release Date	15 <sup>th</sup> August 2022
Build Revision	023db45
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

- 1. The function of Dying gasp added allowing the switch to indicate the power-related downtime
- 2. Added the new algorithm (IP only or Source Port only) for LAG
- 3. Support for 10Gigabit Ethernet port auto linkup added

- 1. 10G ports set with link aggregation did not working after device reboot
- 2. Updated HTTPS mechanism to address the CVE-2022-0778 (OpenSSL)
- 3. The fibre ports media type default setting is set to Auto
- 4. Port Bandwidth Utilization page's colours match the Dashboard
- 5. The RADIUS settings disappeared after restarting the switch
- 6. The status information of the SFP optical module improvements
- 7. The VLAN interface uplink TPID setting could not be stored by the switch

Firmware Version	2.6.8 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	02 <sup>nd</sup> June 2021
Release Date	12 <sup>th</sup> July 2021
Build Revision	bf398b9
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

(none)

- 1. [DHCP] > [Bind IP to MAC] list can be saved to .csv file
- 2. Improved fan control mechanism

Firmware Version	2.6.7 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	26 <sup>th</sup> January 2021
Release Date	16 <sup>th</sup> April 2021
Build Revision	1959
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

(none)

### **Improvements**

1. Updated MyVigor authentication method

Firmware Version	2.6.6 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	21 <sup>st</sup> October 2020
Release Date	12 <sup>th</sup> November 2020
Build Revision	1952
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

(none)

- The Switch's self-signed certificate will change upon upgrade for compatibility with new browser certificate requirements.
  Starting from September 2020, many client OS & browsers will limit publicly trusted TLS server certificate lifetime to 398 days or less, and connections will be rejected if certificates exceed this. This firmware patch will automatically re-sign all self-signed certificate lifetimes to 395 days (was 2 years or longer in older versions)
- 2. Support for statistics/counters information for each port on Status page
- Support for editing the port number for HTTP management on [System Maintenance] > [Access Manager]

Firmware Version	2.6.4 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	24 <sup>th</sup> July 2020
Release Date	28 <sup>th</sup> August 2020
Build Revision	1912
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

1. DHCP Relay is now available in [Switch LAN] > [DHCP Server / Relay] section

### **Improvements**

(none)

Firmware Version	2.6.3.1 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	27 <sup>th</sup> July 2020
Release Date	31 <sup>st</sup> July 2020
Build Revision	1913
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

(none)

### **Improvements**

1. The SYS LED would not light up after turning on the switch

Firmware Version	2.6.3 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	19 <sup>th</sup> June 2020
Release Date	10 <sup>th</sup> July 2020
Build Revision	1889
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

(none)

### **Improvements**

1. Improved compatibility between TR-069 and VigorConnect

Firmware Version	2.6.2 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	22 <sup>nd</sup> April 2020
Release Date	15 <sup>th</sup> May 2020
Build Revision	1834
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

(none)

- 1. Loop Protection Per Port Settings added
- 2. [VLAN Management] > [Interface Settings] dashboard panel added
- 3. Improved compatibility between TR-069 and VigorACS
- 4. QoS Basic Mode with Ingress Trust Mode CoS/802.1p-DSCP could not be used

Firmware Version	2.6.1 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	16 <sup>th</sup> March 2020
Release Date	03 <sup>rd</sup> April 2020
Build Revision	1810
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

1. DHCP server can be configured on [Switch LAN] > [DHCP Server]

### **Improvements**

(none)

Firmware Version	2.6.0 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	22 <sup>nd</sup> January 2020
Release Date	2 <sup>nd</sup> March 2020
Build Revision	1763
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

(none)

- 1. Vigor ACS compatibility updated
- 2. Improvements of IP Conflict Detection feature
- 3. Support for VLAN interface on [ONVIF Surveillance] > [Topology] page

Firmware Version	2.5.1 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	06 <sup>th</sup> December 2020
Release Date	10 <sup>th</sup> January 2020
Build Revision	1688
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

- 1. Support for TLS 1.3
- 2. Support for VigorConnect management

- 1. New TR069 parameters added
- 2. Improvements to IP Conflict Prevention
- 3. Improved interoperability of ONVIF Camera Management with Milesight IP cameras

Firmware Version	2.5.0 (Formal Release)
Release Type	First Firmware Release
Build Date	5 <sup>th</sup> May 2019
Release Date	2 <sup>nd</sup> August 2019
Build Revision	1421
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

#### **First Firmware Release**

[END OF FILE]