

Release Notes for DrayTek VigorAP 802 (UK/Ireland)

Firmware Version	1.3.1
Release Type	Initial Release
Release Date	18 th September 2019
Build Date	27 th May 2019
Revision	10952
Applicable Models	VigorAP 802
Locale	UK Only

First Firmware Release for this model

Known Issues

1. Multi-SSID over Mesh is not supported in this firmware version.
The feature will be available in the next firmware release.

Firmware File Types

The file name of the firmware controls which upgrade type is performed. If the file name is unchanged (e.g. xxxx.all) then the upgrade will just upgrade the firmware, whereas renaming the firmware to a .rst extension will wipe all settings back to factory defaults when upgrading the firmware.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the AP's system maintenance menu.

To upgrade firmware, select '*firmware upgrade*' from the AP's system maintenance menu and select the correct file. The access point will perform the upgrade and automatically reboot once this completes.



Manual Upgrade

If you cannot access the AP's menu, you can put the AP into 'TFTP' mode by holding the FACTORY RESET button whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier.

[END OF FILE]