

Release Notes for DrayTek Vigor2766 series (UK/Ireland)

| | |
|-------------------|--|
| Firmware Version | 4.4.2_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 17 th May 2022 |
| Release Date | 13 th June 2022 |
| Revision | 3596_a57ba5a9ff |
| Applicable Models | Vigor2766, Vigor2766ac, Vigor 2766Vac |
| Modem Code | 1232305 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Improved Web GUI Security
2. Updated HTTPS mechanism to address the CVE-2022-0778 (OpenSSL)
3. Management Access List now supports IP Objects and IP Groups
4. MAC addresses of clients using IGMP queries are displayed in
[Diagnostics] > [Syslog Explorer]
5. PPPoE option is now available for ADSL mode

Known Issues

(None)

Firmware File Types

The ZIP file contains the firmware with two different file extensions, .ALL and .RST. The firmware is identical, but the RST file contains factory default settings. If you install the ALL file, your router will retain all existing settings. If you use the RST file, all settings will be wiped from your router.

Modem Codes

There are three firmware variants available for download.

| Download Filename | Firmware Filename | Modem Code | |
|--------------------|-------------------------|------------|----------|
| | | VDSL | ADSL |
| v2766_442_BT.zip | v2766_442BT_1232305.all | 1232305 | 12321014 |
| v2766_442_MDM0.zip | v2766_442_1232302.all | 1232302 | 12321030 |
| v2766_442_MDM1.zip | v2766_442_12611012.all | 12611012 | 12601015 |

We recommend using firmware "v2766_442BT_1232305.all" unless you have specific line issues.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the router's system maintenance menu.

To upgrade firmware, select '*firmware upgrade*' from the router's system maintenance menu and select the correct file. Ensure that you select the ALL file unless you want to wipe out your router's settings back to factory default.



Manual Upgrade

If you cannot access the router's menu, you can put the router into 'TFTP' mode by holding the RESET whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier and recommended – this manual mode is only needed if the web interface is inaccessible.

| | |
|-------------------|--|
| Firmware Version | 4.4.1_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 14 th February 2022 |
| Release Date | 25 th March 2022 |
| Revision | 2972_7698bd3923 |
| Applicable Models | Vigor2766, Vigor2766ac, Vigor 2766Vac |
| Modem Code | 1232305 |
| Locale | UK & Ireland Only |

New Features

1. Remote management profile supports the Time-based One-time Password (TOTP) authentication method

Improvements

1. Static route sessions can be processed by hardware acceleration
2. Mesh Root TCP port 9608 could be detected on WAN when enabled
3. Dynamic DNS (DrayDDNS profiles) can be set in round robin or WANx First configuration
4. Routers did not connect to GenieACS servers

Known Issues

(None)

| | |
|-------------------|--|
| Firmware Version | 4.4.0_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 25 th November 2021 |
| Release Date | 24 th December 2021 |
| Revision | 2890_79d39042b4 |
| Applicable Models | Vigor2766, Vigor2766ac, Vigor 2766Vac |
| Modem Code | 1232305 |
| Locale | UK & Ireland Only |

New Features

1. App-level Bandwidth Limits (e.g. Teams, OneDrive, Steam) can now be configured from [Bandwidth Management] > [Bandwidth Limit] > [APP]
2. Inbound QoS now supports Hardware Accelerated operation
3. [Certificate Management] system now operates in a new way:
 - a. HTTPS certificate for management & SSL VPN is now selected from: [Certificate Management] > [Local Services List]
Reboot the router after changing this setting to use the new certificate
 - b. [Local Certificates] now supports more than 3 certificates
 - c. [Trusted CA Certificates] now supports more than 3 certificates
 - d. Storage for Certificate on each of those pages shows % remaining available space
 - e. Password on Private Key is no longer required when importing Cert + Private Key
4. Wake on LAN via WAN can now be enabled/disabled for allowed IPs or any WAN IP from [Applications] > [Wake on LAN/WAN] – Wake on WAN tab
5. Support for IKEv2 fragmentation to improve IKEv2 EAP compatibility
6. Router's DNS server feature can record one domain with multiple IP addresses
7. Support for network monitoring protocol IPFIX (Netflow)
8. Firewall can restrict/drop unwanted inbound WAN traffic such as VPN requests
9. SNMP 'ifLastChange' is now supported for WAN and LAN port uptime (Physical port link up/down detection)
10. Webhook feature can now be enabled in [System Maintenance] > [Webhook] to send periodic keepalive / heartbeat messages to a monitoring server
11. Cache password for auto reconnect option added on the [VPN and Remote Access] > [OpenVPN] > [Client Config] page

Improvements

1. DNS Filter now supports blocking of DoH (DNS over HTTPS) and DoT (DNS over TLS) services to ensure that users use standard DNS, allowing the DNS Filter to operate optimally
2. Hardware Acceleration is now enabled by default for new routers & factory default settings
3. Exception list added to [Hardware Acceleration]
4. Updated MyVigor authentication method used for Web Content Filter license validation
5. Support for ADSL PPPoE LLC Line (MDM1 firmware)
6. Improved performance for Hotspot Web Portal
7. Wake on LAN via WAN did not work after rebooting the router

8. Syslog now reports more details for unsuccessful OpenVPN connections
9. Configuration files from Vigor 2765 series can now be restored to Vigor 2766 series routers
10. Function priority and default value change for DoS & Bandwidth Limit and HW NAT settings
11. When Brute Force Protection is disabled, service options are greyed-out (ticked by default)
12. In some circumstances Conditional DNS Forwarding did not work
13. Improved mesh network connectivity
14. Fixed a display issue with Basic Configuration Sync in the Mesh setup section
15. Self-sign certificate renewal mechanism improvements related to DrayDDNS Let's Encrypt
16. Disabling a static route could disable the default route entry
17. After the firmware upgrade, router could stop responding if VoIP call, and VLAN configuration were in use
18. Self-signed certificate will now automatically regenerate before expiring
19. Customized List data information display issue fixed for [LAN] > [General Setup], DHCP Server Option section

Known Issues

(None)

| | |
|-------------------|--|
| Firmware Version | 4.3.2.1_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 26 th October 2021 |
| Release Date | 11 th November 2021 |
| Revision | 10746_1812_a560c17e45 |
| Applicable Models | Vigor2766, Vigor2766ac, Vigor 2766Vac |
| Modem Code | 1232305 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Self-signed certificate will automatically regenerate before expiration
2. System stability improvements
3. Hardware Acceleration did not work with WAN to LAN sessions in routing mode

Known Issues

(None)

| | |
|-------------------|--|
| Firmware Version | 4.3.1.2_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 29 th September 2021 |
| Release Date | 20 th October 2021 |
| Revision | 10306_1798_42887b3b41 |
| Applicable Models | Vigor2766, Vigor2766ac, Vigor 2766Vac |
| Modem Code | 1232305 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Wireless security configuration improvements related to encrypted WDS mode

Known Issues

(None)

| | |
|-------------------|---------------------------------------|
| Firmware Version | 4.3.1_BT (Formal Release) |
| Release Type | Initial Release |
| Build Date | 26 th April 2021 |
| Release Date | 8 th September 2021 |
| Revision | 6988_1790_7d830fb99 |
| Applicable Models | Vigor2766, Vigor2766ac, Vigor 2766Vac |
| Modem Code | 1232305 |
| Locale | UK & Ireland Only |

First Firmware Release for this model

New Features

(None)

Improvements

(None)

[END OF FILE]