

## **Release Notes for DrayTek VigorSwitch P1282 (UK/Ireland)**

|                   |  |
|-------------------|--|
| Firmware Version  | 2.8.5 (Formal Release)                               |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Build Date        | 11 <sup>th</sup> April 2023                          |
| Release Date      | 12 <sup>th</sup> May 2023                            |
| Build Revision    | c26610f  |
| Loader Version    | 3.5.3  |
| Applicable Models | VigorSwitch P1282                                    |
| Locale            | UK & Ireland Only                                    |

### **New Features**

(none)

### **Improvements**

1. Fixed an issue where Syslog could use the wrong timestamp

### **Known Issues**

1. Users can't downgrade the firmware below 2.8.x, if the loader version is 3.5.2  
To check the loader version, open the Dashboard page or use this CLI command:  
*show info*
-

|                   |  |
|-------------------|--|
| Firmware Version  | 2.8.3 (Formal Release)                               |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Build Date        | 10 <sup>th</sup> January 2023                        |
| Release Date      | 21 <sup>st</sup> March 2023                          |
| Build Revision    | a452dac  |
| Applicable Models | VigorSwitch P1282                                    |
| Locale            | UK & Ireland Only                                    |

### **New Features**

(none)

### **Improvements**

1. Further improvements to the Web GUI
2. The PoE chip driver upgrade
3. [System Maintenance] > [General] > [Firmware] page can now display the latest firmware version available online
4. Improvements to the renew certificate mechanism

|                   |  |
|-------------------|--|
| Firmware Version  | 2.8.0 (Formal Release)                               |
| Release Type      | <b>Regular</b> – Upgrade recommended when convenient |
| Build Date        | 13 <sup>th</sup> May 2022                            |
| Release Date      | 10 <sup>th</sup> August 2022                         |
| Build Revision    | c286e45  |
| Applicable Models | VigorSwitch P1282                                    |
| Locale            | UK & Ireland Only                                    |

### **New Features**

1. Support the new PoE chip driver

### **Improvements**

1. Improved Web GUI Security
2. Updated HTTPS mechanism to address the CVE-2022-0778 (OpenSSL)
3. The HTTPS management port can be edited
4. Number of entries for the ICP (IP Conflict Prevention) and ICD (IP Conflict Detection) table has been increased to 1024

|                   |                                |
|-------------------|--------------------------------|
| Firmware Version  | 2.6.7 (Formal Release)         |
| Release Type      | <b>First Firmware Release</b>  |
| Build Date        | 15 <sup>th</sup> October 2021  |
| Release Date      | 16 <sup>th</sup> February 2022 |
| Build Revision    | 95993d5                        |
| Applicable Models | VigorSwitch P1282              |
| Locale            | UK & Ireland Only              |

**First Firmware Release**

**[END OF FILE]**