

Release Notes for DrayTek VigorSwitch P1282 (UK/Ireland)

Firmware Version	2.9.5 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	15 th July 2024
Release Date	23 rd October 2024
Build Revision	ef29dcb
Loader Version	3.5.3
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

New Features

(none)

Improvements

1. Improvements to the TR-069 parameter related issues
2. The CPU usage mechanism improvements

Known Issues

1. Users can't downgrade the firmware below 2.8.x, if the loader version is 3.5.2
To check the loader version, open the Dashboard page or use this CLI command:
show info
-

Firmware Version	2.8.5 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	11 th April 2023
Release Date	12 th May 2023
Build Revision	c26610f
Loader Version	3.5.3
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

New Features

(none)

Improvements

1. Fixed an issue where Syslog could use the wrong timestamp

Known Issues

1. Users can't downgrade the firmware below 2.8.x, if the loader version is 3.5.2
To check the loader version, open the Dashboard page or use this CLI command:
show info

Firmware Version	2.8.3 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	10 th January 2023
Release Date	21 st March 2023
Build Revision	a452dac
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

New Features

(none)

Improvements

1. Further improvements to the Web GUI
2. The PoE chip driver upgrade
3. [System Maintenance] > [General] > [Firmware] page can now display the latest firmware version available online
4. Improvements to the renew certificate mechanism

Firmware Version	2.8.0 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	13 th May 2022
Release Date	10 th August 2022
Build Revision	c286e45
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

New Features

1. Support the new PoE chip driver

Improvements

1. Improved Web GUI Security
2. Updated HTTPS mechanism to address the CVE-2022-0778 (OpenSSL)
3. The HTTPS management port can be edited
4. Number of entries for the ICP (IP Conflict Prevention) and ICD (IP Conflict Detection) table has been increased to 1024

Firmware Version	2.6.7 (Formal Release)
Release Type	First Firmware Release
Build Date	15 th October 2021
Release Date	16 th February 2022
Build Revision	95993d5
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

First Firmware Release

[END OF FILE]